

Knobbe Martens Olson & Bear LLP

Intellectual Property Law

10/02/795

C&C
2040 Main Street
Fourteenth Floor
Irvine, CA 92614
Tel 949-760-0404
Fax 949-760-9502
www.kmob.com



Mark J. Kertz

September 29, 2005

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Re: Title: HYDRAULIC CONFIGURATION FOR
INTRAOCULAR LENS SYSTEM
Letters Patent No. 6,858,040
Issued: February 22, 2005
Our Reference: VGEN.008A

Certificate
OCT 07 2005
of Correction

Dear Sir:

Enclosed for filing is a Certificate of Correction in connection with the above-identified patent.

As the errors cited in the Certificate of Correction were incurred through no fault of the Patent Office, enclosed is our check in the amount of \$100. Please charge any additional fees to our Deposit Account No. 11-1410.

An explanation of the errors and the corrections is set forth below.

First Error: Figures 18 and 39 of the Drawings

The application was originally filed with informal drawings. Due to an inadvertent error in the formal drawings that were later submitted, the formal drawings of Figures 18 and 39B did not match the informal drawings of Figures 18 and 39B as filed. The drawings of Figures 18 and 39B set forth in the enclosed Certificate of Correction properly match the drawings of Figures 18 and 39B as filed.

Second Error: Specification Description of Figures 18 and 19

Figures 18 and 19 are described at Column 15, line 60 to Column 16, line 45. Figures 18 (as corrected) and 19 are depicted below:

10/04/2005 AKELECH1 00000011 6858040

01 FC:1811

100.00 DP

OCT 12 2005

San Diego
619-235-8550

San Francisco
415-954-4114

Los Angeles
310-551-3450

Riverside
951-781-9231

San Luis Obispo
805-547-5580




FIG. 18




FIG. 19

The textual descriptions of Figures 18 and 19 contain a minor, obvious error at Column 16, line 10, in that the angles shown at the bottom of the lens system of Figures 18 and 19 are described as being substantially equal. Obviously, they are not. Indeed, the remainder of the description makes it abundantly clear that what is being described is a lens having asymmetry as

Commissioner of Patents


September 29, 2005

Page -3-

viewed from the side, and that is exactly what the Figures depict. The correction to the specification made in the enclosed Certificate of Correction properly describes the angles as being unequal, and makes line 10 consistent with the other 52 lines of text that describe Figures 18 and 19, as well as with the figures themselves.

Respectfully submitted,

Knobbe, Martens, Olson & Bear, LLP



Mark J. Kertz

Registration No. 43,711

Customer No. 20,995

Enclosures

1935276
091505

OCT 12 2005

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,858,040

DATED : February 22, 2005

INVENTOR(S): Nguyen, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the specification, Col. 16, Line 10, delete "substantially equal" and substitute --unequal--.

In the drawings, change Figure 18 and Figure 39B to the following:




FIG. 18




FIG. 39B

MAILING ADDRESS OF SENDER:

Mark J. Kertz
KNOBBE, MARTENS, OLSON & BEAR, LLP
2040 Main Street, 14th Floor
Irvine, California 92614

PATENT NO. 6,858,040